

View of Bank Stabilization at RW-02



SS-42 pad where SVE pad was



Photographic Summary

Luke Air Force Base Five Year Review Photographs 7 and 8